







bei  $n_{Mot} = 1400 \text{ min}^{-1}$   
1400 RPM Input



bei  $n_{Mot} = 2800 \text{ min}^{-1}$   
2800 RPM Input



bei  $n_{Mot} = 4000 \text{ min}^{-1}$   
4000 RPM Input

